




传感器  
**CN1911**



外形尺寸

传感区参数

总计

整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab长度 <i>A</i>	整体厚度 <i>T</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点总数量	单位面积感测点数量
						列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm) 400	(mm) 218	(mm) 246	(mm) 0.35	(mm) 192	(mm) 110	(mm) 2.2	(mm) 3.7	52	(mm) 2.2	(mm) 3.7	30	1560	(感测点/cm <sup>2</sup> ) 7.3
(in) 15.75	(in) 8.58	(in) 9.69	(in) 0.013	(in) 7.56	(in) 4.33	(in) 0.087	(in) 0.147	52	(in) 0.087	(in) 0.147	30	1560	(感测点/in <sup>2</sup> ) 46.3

量程

kPa	3448
psi	500