




CN5050-1 传感器参数



量程

kpa	69
psi	10

外形尺寸

传感区参数

总计

整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab长度 <i>A</i>	整体厚度 <i>T</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点总数量	单位面积感测点数量
						列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)		(mm)	(mm)			(感测点/cm ²)
1000	650	460	0.2	500	500	8.1	9.6	52	8.1	11.4	44	2288	0.91
(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)		(in)	(in)			(感测点/in ²)
39.4	25.6	18.1	0.008	19.7	19.7	0.32	0.38	52	0.32	0.45	44	2288	5.8

