




CN1146 传感器参数



量程	
kpa	5516
psi	800

外形尺寸							传感区参数						总计	
整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab长度 <i>A</i>	斜边高度 <i>BH</i>	整体厚度 <i>T</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点总数量	单位面积感测点数量
							列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)		(mm)	(mm)		(感测点/cm ²)	
800	143	676	40	0.35	111	46	1.4	2.2	52	0.4	1.1	44	2288	41.3
(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)		(in)	(in)		(感测点/in ²)	
31.5	5.63	26.61	1.57	0.013	4.37	1.81	0.055	0.087	52	0.016	0.043	44	2288	267.3

