




CN1616 传感器参数



量程	
kpa	4137
psi	600

外形尺寸							传感区参数						总计	
整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab长度 <i>A</i>	斜边高度 <i>BH</i>	整体厚度 <i>T</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点总数量	单位面积感测点数量
							列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)		(mm)	(mm)			(感测点/cm ²)
800	186	598	21	0.35	162	167	2.9	4.1	40	4.1	5.6	30	1200	4.4
(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)		(in)	(in)			(感测点/in ²)
31.5	7.32	23.54	0.83	0.013	6.38	6.57	0.114	0.161	40	0.161	0.220	30	1200	28.2

