




CN0507 传感器参数



量程

| | |
|-----|-----|
| kpa | 345 |
| psi | 50 |

外形尺寸

传感区参数

总计

| 整体长度 <i>L</i> | 整体宽度 <i>W</i> | Tab长度 <i>A</i> | Tab长度 <i>B</i> | 斜边高度 <i>BH</i> | 整体厚度 <i>T</i> | 矩阵宽度 <i>MW</i> | 矩阵高度 <i>MH</i> | 列 | | 行 | | | 感测点总数量 | 单位面积感测点数量 | |
|------------------|------------------|-------------------|-------------------|-------------------|------------------|-------------------|-------------------|-----------------|------------------|-------------------|-----------------|------------------|--------|------------------------|-------------------|
| | | | | | | | | 列宽 <i>CW</i> | 列间距 <i>CS</i> | 数量 <i>Qty.</i> | 行宽 <i>RW</i> | 行间距 <i>RS</i> | | | 数量 <i>Qty.</i> |
| (mm) | (mm) | (mm) | (mm) | (mm) | (mm) | (mm) | (mm) | (mm) | (mm) | (mm) | (mm) | (mm) | (mm) | (感测点/cm ²) | |
| 400 | 60 | 119 | 176 | 24 | 0.2 | 54 | 75 | 0.8 | 1.8 | 30 | 0.9 | 1.9 | 40 | 1200 | 29.2 |
| (in) | (in) | (in) | (in) | (in) | (in) | (in) | (in) | (in) | (in) | (in) | (in) | (in) | (in) | (感测点/in ²) | |
| 15.75 | 2.36 | 4.69 | 6.93 | 0.94 | 0.008 | 2.13 | 2.95 | 0.031 | 0.07 | 30 | 0.035 | 0.075 | 40 | 1200 | 190.5 |

