




CN0842 传感器参数



量程

kpa	3447
psi	500

外形尺寸

传感区参数

总计

整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab长度 <i>A</i>	整体厚度 <i>T</i>	斜边高度 <i>BH</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点总数量	单位面积感测点数量
							列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm) 1000	(mm) 90	(mm) 520	(mm) 0.22	(mm) 30	(mm) 80	(mm) 429	(mm) 1.2	(mm) 1.8	44	(mm) 6.3	(mm) 8.3	52	2288	(感测点/cm ²) 6.7
(in) 39.4	(in) 3.5	(in) 20.5	(in) 0.009	(in) 1.2	(in) 3.1	(in) 16.9	(in) 0.05	(in) 0.07	44	(in) 0.25	(in) 0.33	52	2288	(感测点/in ²) 43.3

