




CN1026 传感器参数



量程

kpa	3447
psi	500

外形尺寸

传感区参数

总计

整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab长度 <i>A</i>	整体厚度 <i>T</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点总数量	单位面积感测点数量
						列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)		(mm)	(mm)			(感测点/cm ²)
480	112	209	0.2	106	265	1.4	2.4	44	2.6	5.1	52	2288	8.2
(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)		(in)	(in)			(感测点/in ²)
18.9	4.41	8.23	0.008	4.17	10.43	0.055	0.094	44	0.102	0.2	52	2288	53.2

