




CN1915 传感器参数



量程

kpa	3447
psi	500

CN1915

外形尺寸

传感区参数

总计

整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab长度 <i>A</i>	斜边高度 <i>BH</i>	整体厚度 <i>T</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点总数量	单位面积感测点数量
							列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)		(mm)	(mm)		(感测点/cm ²)	
400	200	214	12.5	0.35	194	156	2.9	4.9	40	4.1	6.1	26	1040	3.3
(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)		(in)	(in)		(感测点/in ²)	
15.75	7.87	8.43	0.5	0.014	7.64	6.14	0.114	0.193	40	0.161	0.24	26	1040	21.6

