




CN1920 传感器参数



量程

kpa	3447
psi	500

外形尺寸

传感区参数

总计

整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab长度 <i>A</i>	整体厚度 <i>T</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点总数量	单位面积感测点数量
						列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)		(mm)	(mm)			(感测点/cm ²)
900	200	685	0.23	190	205	3.4	4.4	44	3	4	52	2288	5.7
(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)		(in)	(in)			(感测点/in ²)
35.4	7.9	27	0.009	7.5	8.1	0.13	0.17	44	0.12	0.16	52	2288	36.8

