




# CN1934 传感器参数



量程

kpa	3447
psi	500

外形尺寸

传感区参数

总计

整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab长度 <i>A</i>	整体厚度 <i>T</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点总数量	单位面积感测点数量
						列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm) 600	(mm) 204	(mm) 248	(mm) 0.23	(mm) 196	(mm) 344	(mm) 3.5	(mm) 4.5	44	(mm) 5.2	(mm) 6.7	52	2288	(感测点/cm <sup>2</sup> ) 3.3
(in) 23.6	(in) 8	(in) 9.8	(in) 0.009	(in) 7.7	(in) 13.5	(in) 0.14	(in) 0.18	44	(in) 0.2	(in) 0.26	52	2288	(感测点/in <sup>2</sup> ) 21.4

