




TC0101 传感器参数



量程

kpa	69
psi	10

外形尺寸

传感区参数

总计

整体长度 <i>L</i>	整体宽度 <i>W</i>	Tab长度 <i>A</i>	整体厚度 <i>T</i>	斜边高度 <i>BH</i>	矩阵宽度 <i>MW</i>	矩阵高度 <i>MH</i>	列			行			感测点 总数量	单位面积 感测点 数量
							列宽 <i>CW</i>	列间距 <i>CS</i>	数量 <i>Qty.</i>	行宽 <i>RW</i>	行间距 <i>RS</i>	数量 <i>Qty.</i>		
(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(感测点/cm ²)
400	60	320	0.2	16.4	10	10	1	1.8	6	1	1.8	6	36	30.8
(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)	(in)	(感测点/in ²)
15.7	2.4	12.6	0.008	0.65	0.39	0.39	0.04	0.07	6	0.04	0.07	6	36	204.1

