




# TC1111 传感器参数



量程

|     |      |
|-----|------|
| kpa | 3447 |
| psi | 500  |

外形尺寸

传感区参数

总计

| 整体长度<br><i>L</i> | 整体宽度<br><i>W</i> | Tab长度<br><i>A</i> | 整体厚度<br><i>T</i> | 斜边高度<br><i>BH</i> | 矩阵宽度<br><i>MW</i> | 矩阵高度<br><i>MH</i> | 列               |                  |                   | 行               |                  |                   | 感测点总数量 | 单位面积感测点数量                       |
|------------------|------------------|-------------------|------------------|-------------------|-------------------|-------------------|-----------------|------------------|-------------------|-----------------|------------------|-------------------|--------|---------------------------------|
|                  |                  |                   |                  |                   |                   |                   | 列宽<br><i>CW</i> | 列间距<br><i>CS</i> | 数量<br><i>Qty.</i> | 行宽<br><i>RW</i> | 行间距<br><i>RS</i> | 数量<br><i>Qty.</i> |        |                                 |
| 342              | (mm)<br>157      | (mm)<br>176       | (mm)<br>0.05     | (mm)<br>36        | (mm)<br>111       | (mm)<br>111       | (mm)<br>0.75    | (mm)<br>1.75     | 64                | (mm)<br>0.75    | (mm)<br>1.75     | 64                | 4096   | (感测点/cm <sup>2</sup> )<br>32.7  |
| 13.5             | (in)<br>6.2      | (in)<br>7         | (in)<br>0.002    | (in)<br>1.4       | (in)<br>4.4       | (in)<br>4.4       | (in)<br>0.03    | (in)<br>0.07     | 64                | (in)<br>0.03    | (in)<br>0.07     | 64                | 4096   | (感测点/in <sup>2</sup> )<br>204.1 |

